

GEORGIA ARCHITECTURAL AND HISTORIC PROPERTIES SURVEY-INVENTORY FORM

I. IDENTIFICATION

PROPERTY NAME: _____ HISTORIC NAME: _____

STREET ADDRESS: 405 SUMMERLIN CITY: Valdosta

PRESENT OWNER: T.E. HATCHER ESTATE MAILING ADDRESS: P.O. Box 574

CITY: VALDOSTA STATE: GEORGIA ZIP CODE: 31601

CURRENT USE: RESIDENCE ACREAGE: _____

U.S.G.S. QUADRANGLE Valdosta U.T.M. REFERENCE: _____

V.B.D. OR TAX MAP NUMBER: VA 47 216

II. DESCRIPTION

ARCHITECTURAL DESCRIPTION AND PRESENT CONDITION:

ORIGINALLY A SHOTGUN - HAS BEEN ADDED ON TO MANY TIMES, GABLED AND SHED TIN ROOF. CLAPBOARD AND SHIPLAP SIDING. MODERN WINDOWS. SET ON BRICK PIERS. MODERN SLIDING GLASS DOOR IN SIDE. POOR CONDITION. LOOKS LIKE A SHACK.

III. HISTORY

ORIGINAL OWNER: _____ ORIGINAL USE: RESIDENCE

ARCHITECT/BUILDER: _____ HISTORIC ACREAGE: _____

DATE OF CONSTRUCTION: _____ DATE(S) OF ALTERATIONS: _____

HISTORICAL NARRATIVE (FROM ORIGINS TO PRESENT): _____

IV. SIGNIFICANCE

N.R. AREA(S) OF SIGNIFICANCE: _____ LEVEL: _____

STATEMENT OF SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL): _____

V. SOURCES

FORM PREPARED BY: Smith, Bartholomew ORGANIZATION: South Georgia Area Planning and Development Commission

ADDRESS: 327 Savannah Ave. Valdosta, Ga. 31601 TELEPHONE NUMBER: 912-247-3454 or 3494

REPRESENTATION IN EXISTING SURVEYS: _____

SOURCES OF INFORMATION: _____

PHOTOGRAPHER: **FREDA SMITH**

DATE: **DEC. 1980**

ROLL NO. **F-1A** FRAME NO. NEGATIVES FILED AT: **South Georgia APDC**

DIRECTION PHOTOGRAPHER FACING:

DOOR IN SIDE ROOM CONDITION LOOKS LIKE A SHAK
MODERN WINDOWS. SET ON BRICK PIERS. MODERN SLIDING GLASS
GABLED AND STEEP TYP. CLAPBOARD AND SHIP LAP SIDING
ORIGINAL A SHOTGUN - HAS BEEN ADDED ON TO MANY TIMES

USE SPACE BELOW FOR CONTINUATION FROM FRONT, SKETCH PLANS OR MAPS, ADDITIONAL COMMENTS, ETC.